

Completion Report FRM-144

Project Name: HHIP2300001 Utopia – Clusters 2 & 4

Property Address: House 15, Mosquito Bore Homeland.








Table of Contents

1.	Proj	ect Summary	3
2.	Sco	pe and Visual Confirmation of Works	4
2	2.1	Kitchen & Living Area	4
2	2.2	Bedroom	5
2	2.3	Bathroom & Toilet	7
2	2.4	Laundry, Additional Toilet & External Area	8
3.	Atta	chments	10
;	3.1	Electrical Certificate of Compliance	11
;	3.2	Waterproofing Certification	12
(3.3	Glazing Certification	13

	1
Service Provider	AEA NT PTY LTD
Cervice i rovidei	PO Box 519 Katherine NT 0851
Contact numbers:	(08) 89722 211
Stephen Curry - Technical Services Manager	0427 215 952
Luke Wilks - Senior Project Manager	0476 156 419
John Binns - Project Manager (Central Region)	0427 650 058
Australian Business Number (ABN)	86 009 635 901
Contractor Accreditation Limited (CAL) Registration Number	K-28-10183-07-24
Asset No	House 15, Mosquito Bore Homeland.
Contract No.	HHIP2300001
Completion date	25/06/2024

FRM-144

Completion Report

House 15, Mosquito Bore Homeland



1. Project Summary

House 15, Mosquito Bore Homeland.

The Homelands Housing and Infrastructure Program (HHIP), managed through the Department of Territory Families, Housing and Communities (TFHC) is a program funded by the Australian Government of which is focused on improving the living conditions in Homelands to ensure residents have access to safe, secure and quality housing and infrastructure suitable to their needs.

AEA NT have completed the approved scope of works at House 15, Mosquito Bore Homeland, delivering a quality final product which was handed back to the primary residents who now have improved access to the 9 Healthy Living Practices.

The construction works at House 15, Mosquito Bore Homeland commenced on 27th May 2024 and were completed on 25th of June representing a four (5) week works program.

The total labour hours expended on this project included 40% participation by Aboriginal staff and/or sub-contractors.

House 15, Mosquito Bore Homeland



2. Scope and Visual Confirmation of Works

2.1 Kitchen & Living Area

- Install 2 x new solid core doors including entrance locksets (keyed alike with other external doors), door saver plates, weather seals, and door stops
- Install 1 x new solid core door with passage lockset to existing built-in pantry
- Install 3 x new windows (to suit existing openings), screens and flashings (1 x kitchen window and 1 x living area window without air-conditioning provision; 1 x living area window with box air-conditioner provision ONLY)
- Install curtain rod holders above 2 x living area windows only (holders only NO rods)
- Patch, prepare and paint all surfaces (walls, ceiling, door frames, doors, pantry shelves and window surrounds)
- Remove nib walls, fireplace and chimney; patch walls and floor and tile floor and skirting
- Repair damaged floor tiles including nosing tiles from external slab to weather strip under both external doors
- · Supply and install new stainless steel kitchen benches
- Install new sink and flick mixer
- Install new electrical components including stove and isolator, lights, light switches, ceiling fan, fan switch, power points (including new power point near window with A/C provision in living area), and smoke alarm.
- Replace existing ceiling air-conditioning vents with PVC grid mesh covers
- Paint touchups



House 15, Mosquito Bore Homeland





2.2 Bedroom

Bedroom 1

- Install 1 x new solid core door including privacy lockset and door stop
- Install 1 x new window, screen and flashings with box air-conditioner provision
- Install curtain rod holders above window (holders only NO rods)
- Patch, prepare and paint all surfaces (walls, ceiling, door and window frames)
- Repair damaged floor tiles
- Clean, prepare and repaint existing steel framed mesh cupboard
- Install new electrical components including light, light switch, ceiling fan, fan switch, power points (including new power point near window with A/C provision)
- Replace existing ceiling air-conditioning vents with PVC grid mesh covers
- Paint touchups

Bedroom 2

- Install 1 x new solid core door including privacy lockset and door stop
- Install 1 x new window, screen and flashings with box air-conditioner provision
- Install curtain rod holders above window (holders only NO rods)
- Patch, prepare and paint all surfaces (walls, ceiling, door and window frames)
- Repair damaged floor tiles
- Supply and install new double door steel framed mesh cupboard
- Install new electrical components including light, light switch, ceiling fan, fan switch, power points (including new power point near window with A/C provision)
- Replace existing ceiling air-conditioning vents with PVC grid mesh covers
- Paint touchups

Bedroom 3

- Install 1 x new solid core door including privacy lockset and door stop
- Install 2 x new windows, screens and flashings (only 1 x window with box air-conditioner provision)
- Install curtain rod holders above windows (holders only NO rods)
- Patch, prepare and paint all surfaces (walls, ceiling, door and window frames)
- Repair damaged floor tiles
- Supply and install new double door steel framed mesh cupboard
- Install new electrical components including light, light switch, ceiling fan, fan switch, power points (including new power point near window with A/C provision)
- Replace existing ceiling air-conditioning vents with PVC grid mesh covers
- Paint touchups

House 15, Mosquito Bore Homeland











After Bedrooms works completed:







House 15, Mosquito Bore Homeland



2.3 Bathroom & Toilet

Bathroom

- Strip out bathroom including removing shower hob, wall and floor tiles
- Waterproof wet area walls and floor
- Prepare and lay screed bed with appropriate fall to floor waste
- Tile and grout floors, walls and skirting
- Install 1 x new solid core door including privacy lockset and door stop
- Install 1 x new vented window with screen and flashings
- Patch, prepare and paint all surfaces (walls, ceiling, door and window frames)
- Supply and install new plumbing fittings and fixtures including stainless steel shower mixer, outlet, shower rose, waste grate, stainless steel mixer & hand basin with splash back
- Supply and install new fixtures including towel rail, disabled grab rails, stainless steel soap holder, stainless steel shelves, hooks to back of door
- Install new electrical components including light, switches, power point
- Paint touchups

Toilet

- Install 1 x new solid core door including privacy lockset and door stop
- Install 1 x new vented window with screen and flashings
- Supply and install new plumbing fittings and fixtures including stainless steel mixer & hand basin with splash back, toilet pan, pan rubber, mini cistern cock and toilet roll holder
- Patch, prepare and paint all surfaces (walls, ceiling and new door)
- Repair damaged floor tiles
- Install new electrical components light and switch
- Paint touchups

Before Bathroom & Toilet works commenced: After Bathroom & Toilet works commenced: 25 Jun 2004 of 12:25 de PAI 26 Jun 2004 of 12:25 de PAI 26 Jun 2004 of 12:25 de PAI 27 Jun 2004 of 12:25 de PAI 28 Jun 2004 of 12:25 de PAI 29 Jun 2004 of 12:25 de PAI 20 Jun 2004 of 12:

FRM-144

Completion Report

House 15, Mosquito Bore Homeland



2.4 Laundry, Additional Toilet & External Area

Laundry

- Install 1 x new solid core door including entrance lockset (keyed alike with other external doors), door saver plate, weather seal, and door stop
- Install 1 x new window with screen and flashings
- Patch, prepare and paint all surfaces (walls, ceiling and new door)
- Repair damaged floor tiles including nosing tiles from external slab to weather strip under door
- Supply and install new laundry tub
- Service laundry taps
- Clean, prepare and repaint existing steel framed mesh cupboard
- Install new electrical components including light, switches, and power point
- Paint touchups

Additional Toilet (Outside)


- Install 1 x new solid core door including entrance lockset (keyed alike with other external doors), door saver plate, weather seal, and door stop
- Install 1 x new window with screen and flashings
- Supply and install new plumbing fittings and fixtures including stainless steel mixer & hand basin with splash back, toilet pan, pan rubber, mini cistern cock and toilet roll holder
- Patch, prepare and paint all surfaces (walls, ceiling and new door)
- Repair damaged floor tiles including nosing tiles from external slab to weather strip under door
- Install new electrical components light and switch
- Paint touchups

External Areas

- Remove and replace electric HWS
- Remove old unused/redundant chimney and patch roof and ceiling
- Prep and paint T-bar clothesline uprights and re-string with stainless steel line and tensioner
- Rear verandah pressure clean, prepare, fill cracks, Tuff Top and grind concrete slab
- Front verandah pressure clean, prepare, fill cracks, Tuff Top and grind concrete slab; remove 1 x nib wall return at one end to allow access to front verandah; slats to be installed above existing nib wall (1200 high) only at dog legged returns on both ends of front verandah
- Pressure clean, prepare and paint external wall surfaces, posts and frames
- Provide 2 x concrete splash pads to suit existing outside garden taps
- Install new main water valve box with 600mm concrete surround
- Supply and install 6 x new yellow painted bollards around septic tank
- Install new electrical components including lights, switches, power points, meter isolator, RCDs, and compliant switchboard
- Service "swampy" air-conditioning unit (NOT split system)

House 15, Mosquito Bore Homeland





FRM-144

Completion Report

House 15, Mosquito Bore Homeland



3. Attachments

Electrical Certificate of Compliance Water Proofing Certification Glazing Certification

House 15, Mosquito Bore Homeland



3.1 Electrical Certificate of Compliance

Contractor Name:	Cla. I	Tale Address	to the second second	Lal	
PWC NIW No:	Dray Li	+ Electric	entractor Involce	TCI .	(F) (F) (F)
Installation Det	Aborigina	Entern	TISES A	stralia	
Address - Installation Address - Postal	La 15	masquitto	Bore, S	andover	NT.
Telephone (a/h):		Te	lephone (b/h):	89	72 2211
Type of Installation Wo	ork (tick appropriate boxes	1	Alterations	[≱Res	pairs
Describe Work	Certified - ATTACH	OTHER SHEETS AS	S REQUIRED		
Keplacec	1 all elec	HICUI	appear	10505	Ill icico.
001-01	2	la anc	000	poleci.	
2	al adain	Footh	and I	nstalle	Cl .
HEALAAR	A STATE OF THE PARTY OF THE PAR				
Replace	CA IMIGHT	china	instal	had so	ite tu.
Mechanic	cal prote	ction.	insta	lled so	ate ty al
Replace Mechanic Switches	on all	CITCOIN	insta s. Insta	lled so	old, tional
Switches	on all	CITCOIN	2' 1112"	The Contract	
Switches	coil protes son all here nee	CITCOIN	2' 1112"	lled so alled a stest4	
SWITCHES SPOS Wh Non-Compliance	on all here hee es observed on ex	ded. A	I Works	test4	Comply.
SW (4ches gpo/s wh Non-Compliance QUOTE STANDARD &	on all nere need on exclause number for	ded. A	I Works	test4	Comply.
SWITCHES SPOS Wh Non-Compliance	os observed on ex cLAUSE NUMBER FO ity Safety Regulator	ded A	WOLKS	test4	Comply.
SW (16 hes gpo/s wh Non-Compliance QUOTE STANDARD &	os observed on ex cLAUSE NUMBER FO ity Safety Regulator	ded A	WOLKS	test4	Comply.
SW (16 hes gpo/s wh Non-Compliance QUOTE STANDARD &	os observed on ex cLAUSE NUMBER FO ity Safety Regulator	ded A	WOLKS	test4	Comply.
SW (16 hes gpo/s wh Non-Compliance QUOTE STANDARD &	os observed on ex cLAUSE NUMBER FO ity Safety Regulator	ded A	WOLKS	test4	Comply.
SW (1ches 3PG/S Wh Non-Compliance QUOTE STANDARD & Reported to Electric	os observed on ex cLAUSE NUMBER FO ity Safety Regulator	ded. A	WOLKS	test4	Comply.
SW (+ches 3PO'S Wh Non-Compliance DUOTE STANDARD & Reported to Electric	os observed on ex clause number for ity Safety Regulator	ded A	WOLKS	test4	Comply . red AS REQUIRED
Non-Compliance OUOTE STANDARD & Reported to Electric	es observed on ex clause number for ity Safety Regulator	ded Aldisting installar NON-COMPLIAN	NOI WOLKS	rere not repail OTHER SHEETS	Comply . red AS REQUIRED
Non-Compliance OUOTE STANDARD & Reported to Electrical	es observed on ex cLAUSE NUMBER FO ity Safety Regulator	ded Allering Installar NON-COMPLIAN	tion which w	Cicence No.	Comply - red As REQUIRED
Non-Compliance OUOTE STANDARD & Reported to Electric Reported to Electric Reported to Electric Reported to Electric	es observed on ex cLAUSE NUMBER FO	ded, All string installar NON-COMPLIAN Served	tion which w	Cicence No.	Comply - red AS REQUIRED A 12 66) nd tests on the electrical onn Act 2000.
Non-Compliance QUOTE STANDARD & Reported to Electric Reported to Electric Retailation work detailed	es observed on exception of the complete and the complete	ded, Allisting installar NON-COMPLIAN Served	tion which wices – ATTACH	Licence No:	Comply - red As REQUIRED
Non-Compliance DUOTE STANDARD & Reported to Electric	es observed on exception of the complete and the complete and to this conficate, and the confised Agent actions are confised Agent actions and the confised Agent actions are confised Agent actions are confised Agent actions and the confised Agent actions are confised actions and confised actions are confised actions are confised actions are confised actions and confised actions are confised actions are confised actions are confised actions and confised actions are confised actions are confised actions and confised actions are confised actions are confised actions and confised actions are co	ded, Allisting installar NON-COMPLIAN Served correct and that I he results satisfy a Signature	tion which wices – ATTACH	Licence No:	Comply - red As REQUIRED A 12662 ad tests on the electrical form Act 2000. Date: 22/6/2
Non-Compliance DUOTE STANDARD & Reported to Electric	es observed on ex clause number for ity Safety Regulator (WOCO)- Ormation is complete and on this certificate, and it herwood- thorised Agent ac agent ac agent is corrected and to the control of the	ded A Isting installar NON-COMPLIAN Served I correct and that I he results satisfy a Signatus Signatus Signatus	tion which wices – ATTACH	Licence No:	Comply - red As REQUIRED A 12662 ad tests on the electrical form Act 2000. Date: 22/6/2
Non-Compliance DUOTE STANDARD & Reported to Electric Reported to Electric	es observed on exception of the complete and the complete	ded A Isting installar NON-COMPLIAN Served I correct and that I he results satisfy a Signatus Signatus Signatus	tion which wices – ATTACH	Licence No. In all examinations are the Electricity Ref	Comply - red As Required As 12 66 2 not tests on the electrical ont Act 2000. Date: 22/6/2
Non-Compliance DUOTE STANDARD & Reported to Electric Reported to Electric	es observed on ex clause number for ity Safety Regulator Observed	ded, Allisting installar NON-COMPLIAN Served decorrect and that I he results satisfy a Signature string on the Correct and that I have Act 2000 CICAL All Served	tion which wices – ATTACH	Licence No: all examinations are the Electricity Refu	Comply - red As REQUIRED A 12662 ad tests on the electrical form Act 2000. Date: 22/6/2
Non-Compliance DUOTE STANDARD & Reported to Electric	es observed on ex clause number for ity Safety Regulator Observed	ded A Isting installar NON-COMPLIAN Served I correct and that I he results satisfy a Signatus Signatus Signatus	tion which wices – ATTACH	Licence No. In all examinations are the Electricity Ref	Comply - red As Required As 12 66 2 not tests on the electrical ont Act 2000. Date: 22/6/2

House 15, Mosquito Bore Homeland



3.2 Waterproofing Certification

Waterproofing Certificate



Certification - Waterproofing of Wet Areas

Property Details	
Lot:	House is.
Street Address:	Musquito Bore
Owner:	

Signature: D.M. Squall.

Date: 24 / 05 / 2024.

House 15, Mosquito Bore Homeland



3.3 Glazing Certification

NORTHERN TERRITORY OF AUSTRALIA BUILDING ACT

MANUFACTURER'S CERTIFICATION-WINDOWS / DOORS / SHOWER SCREENS

PROPERTY / PROJECT DETAILS								
Owner (if known):								
Lot/Portion Number:			Address:					
Location: House 15, Mosquit	o Bore		Town / Hun dred :					
Building Permit Number:								
Windows/Doors/Shower Screens man	ufactured to the	e followi	ng criteria					
Location in Building (floor level)		Ground	i	First	Second			
 Serviceability design pressure(s) kF 	a		N3CW/2N					
 Utimate design pressure(s) kPa 			1000 PA					
 Water penetration test pressure Pa 			150 PA					
 Localised pressures*(if applicable) kPa 								
Or window schedule certified by structural engineer			☐ Attached (tick if attached).					
Criteria obtained from								
building permit (approved drawings) ref no: structural engineer section 40 design certificate NTDTC sheet W412/1 or 2								
Window Fixing					with this certificate.			
Comments/Exclusions	Exclusions to the	his certif	icate must be dear	ly iden tified and certifie	d separately.			
CERTIFICATION Manufacturer		Addre						
K&S WINDOWS		Addre		N STREET				
Phone 8952 3472		Email	aumin@kanu	swindowsnt.com				
NT Building Act and the attached fixing construction to AS2047, Glazing to AS	I certify that the "windows/doors/shower screens described above have been manufactured in accordance with the requirements of the NT Building Act and the attached fixing details are appropriate to the windows and/or doors for their location. INCLUDES – Window construction to AS2047, Glazing to AS1288, human impact in accordance with AS1288, fixing details provided are adequate for wind loads and allowance for increased pressures adjacent corners of buildings.							
Name CHRISTOPHER KROI	LLIG	Positi		/ DIRECTOR				
Signature			25 /0	6/2024				
Installation								
I certify that the *windows/doors/shower accordance with the attached fixing de		ed above	have been installe	ed appropriately to their	location in the building and in			
[] Builder		Signature			Date			
OR		 						
[] Manufacturer			Signature		Date			
OR								
[] Section 40 certificate			To be attached					

Delete as applicable March 2013